

bosal

**Инструкция по монтажу
тягово-цепного устройства
шарового типа 3307 А
для автомобилей
GREAT WALL
HOVER**



	2010 -...
	1500
	75
	23

+7 (495) 6-693-693

www.magfarkop.ru
magfarkop@yandex.ru

462800,

18
: (35363) 7-05-06
/ : (35363) 7-13-20
(495) 785-66-07
www.bosal-autoflex.ru


« - - - » (8182) 22-48-15
" " 8(8442) 98-74-98
" " 8(343) 379-39-89, 373-42-73
" " 8(343) 26-88-308
" " 8(3952) 710-194
" " 8(495) 777-54-59
" " 8(495) 745-79-11
" " 8(495) 788-95-97
" " 8(495) 720-51-03
" " 8(3532) 57-99-85
" " 8-905-899-5012
" " 8(383) 291-59-60
" " 8(831) 279-53-24
" " 8(3422) 98-27-20
" " 8(342) 220-87-87
" " 8-927-002-90-06
" " 8(3462) 24-00-44
" " 8(3842) 21-14-76
" " 8-902-940-4151
" " 8(3452) 32-22-12, 41-52-62
" " 8-961-213-0278
" " 8-917-347-1700
" " 8(351) 269-44-75, 900-72-73
" " 8(3512) 773-76-91

41.55-2005.

МАГАЗИН ФАРКОПОВ

+7 (495) 6-693-693

www.magfarkop.ru
magfarkop@yandex.ru




Ø13

Ø18

2


56

1		
2		
3		
4		
5		
6		
7		



	1
	1
	1
	1
	1
	1

Схема обрезки кабеля



12 40	4
12 1,25 90	2
12 120	3
12 130	3
12	8
12 1,25	2
12	2
12	16
12	2
40 40 3	6
86	3
56	2
Ø13 Ø30 l=40	4
	2
VH 0804	1
	1
	1
	1
190	1
	3
	1