

M10x30 - 8ks  
M12x70 - 2ks (A)  
M12x90 - 2ks (I)  
M12x19 - 3ks (C)  
M12x21 - 1ks (C)




M10 - 4ks  
M12 - 2ks (A, I)




PP10 - 8ks  
PP12 - 2ks (A, I)  
PP12 - 4ks (C)


C




M12x19 - 3ks  
M12x21 - 1ks



MODEL 2001-2009



MODEL 2010-



M12x90 - 2ks



M10x30

M10x30

B

M12x70 - 2ks

CITROEN C3  
Kód: C0486(A,I,C) - 4. 5. 2010

A

#### NÁVOD NA MONTÁŽ:

Kód: C0486(A,I,C)

■ 1. Uvoľnite plastové kryty batožinového priestoru. ■ 2. Demontujte zadné svetlá a zadný nárazník. Odstráňte fólie v zadnej časti nosníkov, pod ktorými sú umiestnené upevňovacie otvory ťažného zariadenia. ■ 3. Ťažné zariadenie montujte po častiach. Na upevňovacie otvory zľahka priskrutkujte postranné pätky A a na ne naskrutkujte rám ťažného zariadenia B. Vzhľadom na voľné uloženie ťažné zariadenie ustavte do správnej polohy a následne skrutkové spoje dotiahnite momentom podľa tabuľky. ■ 4. Zapojte vodiče elektroinštalácie podľa návodu. ■ 5. Skontrolujte správnosť pripojenia elektroinštalácie. ■ 6. Namontujte späť zadný nárazník a ďalšie demontované diely. ■ 7. Upevnite spojovaciu guľu a skontrolujte dotiahnutie skrutkových spojov spojovacej guľe (držačka spojovacej guľe) momentom podľa tabuľky.

#### FITTING INSTRUCTIONS:

■ 1. Remove the plastic cases of the baggage compartment. ■ 2. Remove the back lights and the rear bumper. Take off the foils in the back part of the bars – there are situated the fixing holes of the tow-bar under these foils. ■ 3. Install the tow-bar in parts. Freely screw the side base A on the fixing holes and then screw the frame of the tow-bar C on it. Because of the free replacement fix the tow-bar into the regular position and then tighten the screw connections by the torque table. ■ 4. Connect the electrical installation conductors as described in the instructions for use. ■ 5. Check the accuracy of electrical installation connection. ■ 6. Replace the rear bumper and the next disassemble parts. ■ 7. Fix the linkage ball and check all the screw connections of the linkage ball by the torque table.

#### DŮLEŽITÉ UPOZORNENIA:

- V miestach stykových plôch sa musí odstrániť pružná ochrana karosérie vozidla.
- Vŕtané otvory treba ošetriť antikoróznou hmotou.
- Použite len dodaný spojovací materiál v predpisanej triede kvality.
- Elektrické zariadenie sa namontuje podľa podmienok prevádzky cestných vozidiel na pozemných komunikáciách.
- Údaj S o maximálnom zvislom zaťažení na guľu je uvedený na výrobnom štítku ťažného zariadenia.
- Na ťažnom zariadení nie je možné nič upravovať ani meniť.
- Pred ukončením montáže je nutné prekontrolovať všetky spoje podľa tabuľky uťahovacích momentov!
- V prípade akýchkoľvek nejasností je nutné obrátiť sa na výrobcu ťažného zariadenia.
- Výrobca nenesie zodpovednosť za škody spôsobené nesprávnym použitím výrobku.

#### IMPORTANT ATTENTIONS:

- Remove insulating material on a car body in grips and joints of a coupling device with a car body.
- Put the anticorrosive substance on the drilled holes.
- Use supplied mechanical strength jointing material.
- Wiring of a coupling device must be up to a standard and car maker requirements.
- Statement S about the maximum vertical ball downtake is printed on the tow bar label.
- On the tow bar is no modification possible
- Check all the joints, look in the table of the spining moments, before finishing the montage!
- Contact the tow bar marker with any questions.
- The manufacturer is not responsible for the damages caused by wrong using on the product.

Tabuľka uťahovacích momentov skrutkových spojov pevnosti 8.8 / Table of specified torque and hardenss settings 8.8

**M6** - 9,5Nm, **M8** - 23Nm, **M10** - 46Nm, **M10x1,25** - 49Nm, **M12** - 79Nm, **M12x1,25** - 87Nm, **M12x1,5** - 83Nm, **M14** - 125Nm, **M16** - 195Nm